In PECTION REPORT REVIEW POTENTIAL HAZARDOUS WASTE SITE

(319)

SITE NAME : HOUSTON GAS LIGHT COMPANY LOCATION : HOUSTON SITE NUMBER: TXD981918188
SURVEY DATE: 4/6/88
LABORATORY: ____CLP STATE (FIT) TAT INSPECTED BY: EPA Sjena Ed RECEIVED FROM: SAMPLE TYPE(s): SURFACE WATER GROUND WATER DRINKING WATER off / on -site off / on -site off / on -site CONTAMINANT(s): (Organic)s Inorganics Radionuclides Microbiological FOLLOW UP (Y/N): Notate Drinking Water Sources
Keep Site Active ("N"=No Further Action)
Concur with Report Recommendations (Re)Sampling Requested
Further Action is URGENT SUMMARY: This report involves an old cool 3-13 ification plant site that has been closed since me site is in do-interper Houston And is mostly covered over with povement. Soil sampling revealed high Polymeleon from tic hydro cor bons. Superfund review colls for further invostigation. I some the exposure to workers stondgraint and other quality frectors. The site to drinking water supplies, Although the city of Houston hoes ground voter and has some of its town they are quite deep they are quite had any water quality to not further ~ Fill onen Nouis 2,12,90

Concurrence:

Golgon Ar Joffy for T.L. Z.1 13 190